

V. ORLANDI

S I S T E M I D I T R A I N O

Brescia, 21st May 2013

PRODUCT IMPROVEMENT NR.	01062013
PRODUCT	E50 / E50 PACIFIC / UN766

Dear Partner,

As part of our continuous improvement program, we have made the following change:

OLD PART NUMBER	RG00174/RG00222/RG00373/RG00424
NEW PART NUMBER	RG00583/RG00352/RG00372/RG00423
FROM DELIVERIES	June 2013

Photo (Old)





Photo (New)



EVENTUAL OTHER TECHNICAL NOTES:

From the above picture the red colored front flange won't be part anymore of the below listed kit:

- RG00174 will become **RG00583** – to suits **E 506**
- RG00222 will be replaced by **RG00352** – to suits **E 509** and **UN76602**
- RG00373 will be replaced by **RG00372** – to suits **E 510**
- RG00424 will be replaced by **RG00423** – to suits **E 520 PACIFIC**

All the above mentioned kit will be supplied without the front flange.

From 1st of June the below products will be supplied without the front flange:

- E50 – **GE506A0/B0, GE509A0/B0, GE510A0/B0**
- E50 PACIFIC – **GE520A0/B0/E0/F0**
- UN766 – **UN76602**

For eventual further information, please contact our Sales Department